

Underground Storage Tank Impressed Current Cathodic Protection **Evaluation Checklist**

I. UST Facility							II. UST Owner					
Facility Complia	nce	Tag #	¥: 1	363			Name: Shop Stop	LLC				
UBI: 60287942	5						Address: 1611 S.	Canyo	n			
							City: Ellensburg		State: WA	ZIP: 98926		
Facility Name:	Flyin	gB#	29	!			Phone: 509-925-9	270				
Address: 1611	_	-		1		***	III. CP Tester					
City: Ellensburg			_			27.0	Tester's Name: Ke	evin W	ilkerson	*		
County: Kittata	-	in the		2			Company Name: NES, Inc					
State: WA						***	Address: POB 158					
ZIP: 98926			***			***	City: Summer		State: WA	ZIP: 98390		
Phone: 509-925	-927	0					Phone: 253-241-62	213	-			
							Certification Type:			2000		
							Certification Numb		12674	Exp: 01/12		
Tar Tilla di di esc. I			Į.	IV.	Cat	hodic Protect	tion Tester's Eva			Tap. Oares		
	ass ail	by	y th	e Wasi	hingtor	n State Undergro	aluate whether cathod und Storage Tank Re stionally recognized a	egulatio	ons, were in acco	ordance with a		
CP Tester's Sign	natu	re:		1	1		93	20 BERGERS	CP Survey Per	formed;		
			\leq	1		W Dotnoët o	or Repair Design	5/11	/11			
Checklist. Corrosion Exper	0 1					- Congrituing of the	National Recognize					
Company Name	£.			i i		+	Certification Number:					
Corrosion Exper	t's S	Sianati	ure			V	Date:					
				1.	VI.	Criteria Appl	licable to Evaluation					
Continuity Test		Ø		SS 🗆			t show continuity usin		pproved testing	method		
Neg. 850	x			Pass Fail	Tani		polarized potential o					
Instant Off	х			Pass	Pipir		copper-copper sulfate	refere	nce electrode (l	nstant Off		
100 110 1	х	3	X	Pass	Tani	ks A minimum	n of 100 mV of cathoo	dic note	arization between	n the structure		
100 mV Pol.	x	2	_	Pass Fail	Pipir	nurfoes on	d a stable reference of	TO STATE OF THE ST				
	591				tion	Required as	a Result of this !	Evalu	ation	et a		
M NONE						Cathodic Protect	ion is adequate. No fi	urther a	action is necessa	ary at this time.		
RETEST				-12			ion may not be adequ					
RETROFIT/	e typ	oe of	gea	r, Ex:	ST (Cathodic Protect	ion is not adequate. III and McMiller - Te	Retrofr	tting or Repairin	g is necessary		
							2 8					

	a at e	183	VIII.	Impresse			- 1	a	, 1	5 5 4
Rectifier Manufacture	г	Unive	rsal		Rec:	ifier Mo aber	del	SSP		
Rated DC O	atput	4 <u>8</u> <u>8</u>	11120	olts nps	Rec	tifier Ser aber	ial	881571		
Rectifier "A	s Found	" Data								
(*) AC Input	Voltage	,		Volts	DC	Voltage	on Panel	Meter	46	Volts
(*) AC Step-	Down V	oltage	-	Volts		Voltage out Term	on Recti	fier	46.6	Volts
Tap Settings		C-	4	F-1	DC	Amps or	Panel N	1eter	1	Amp
16	Secon	ndary Ta	ips	Hz	(*)	Shunt F	lating		50/1	0
(*) Cycles	200				(*)	Shunt N	16	mV		
	DC C	Output	H	Z	DC	Amps fr	om Shun	t Reading	<u>.8</u>	Amp
Rectifier "A	s Left" (Data								k:
(*) AC Input	Voltage			_ Volts	DC	Voltage	on Panel	Meter	46	Volts
(*) AC Step-	_ Volts	10	Voltage out Term	on Recti	fier	46.6	Volts			
Tap Settings	S C-4 F-1 DC Amps on Panel Meter						1	Amp		
	Secon	ndary Ta	ips	Hz	(*)	Shunt P	lating		50/1	0
(*) Cycles	DC C	Output _	н	z		(*) Shunt Measurement DC Amps from Shunt Reading				mV Amp
	Complet	e only if	Anod		ements Found	can be	taken ir	ndepender		
Anode #	1	2	3	4	5	6	7	8	9	10
Volts Amps		- 1				-			-	-
· · · · · ·				",	s Left"					
Anode #	1	2	_ 3	4	5	6	7	8	9	10
Volts Amps			10-2							
X.	Remark her:	s (Desc	ribe ar	ny modifi	cations	that we	re made	to the CF	Syste	n)

Structure A"	Structure "B"	Point "A" "B" or Fix	red Cell	Structu Fixe Voltage	ed	Structure Fixed Voltage -	1	Point to Fixed V Differ	oltage	1739	ass or Fall?	Method and Standard Used (e.g. RP-0285, R051)
			190000 1 100		- 00	07 07 150	- 00		01100	×	Pass	
1D-Riser	Turbine	NW Con	ner (30)	1.568		1.566		002		X	Fail Pass	Fixed R051
2U-Riser	Turbine	."		1.567		1.566		001			Fall Pass	
3S-3" Сар	Turbine	in .		1.569		1.569		000			Fail Pass	er
1D-Riser	Negative	in .		1.568		1.568		000			Fail	н
2U-Riser	Negative	."	1.		1.567 1.566			001			Pass Fall	n
3S-Riser	Negative		1.			1.569		000			Pass Fail	•
2U-Riser	N-Disp PL			1.567		1.564		003		×	Pass Fail	"
		97			,			004		\otimes	Pass	п
2U-Riser	C-Disp PL	i		1.567		1.563	-	9000		×	Fail Pass	
2U-Riser	S-Disp PL	- "	_	1.567		1.567		000			Fail Pass	"
3S-Riser	N-Disp PL	!"		1.569		1.569		000			Fail Pass	"
3S-Riser	C-Disp PL			1.569		1.569		000			Fail	n
3S-Riser	S-Disp PL			1.569		1.568		001			Pass Fall	Fixed R051
											Pass Fail	
		100									Pass Fail	
7 76 4	x	II. Impres	sed C	urrent	Cath	odic Pr	otec	tion Sys	tem Su	Phone		
Structure	Contact Point	Half Cell Location	Local	Voltage	Loca	I Voltage	Loc	cal Voltage	Voltage Change	T	Pass or Fail?	Method and Standard Used
UST 1-D	Turbine	NW (30)	-1.567		674		-,565		109mV	1	⊠ Pass ☐ Fall	100 mV Pol RP0285
UST 2-U	4" Cap		-1.567	8	629	í .	51	.0	119mV		⊠ Pass □ Fail	•
UST 3-S	3" Cap	11	-1.569		671		56	1	110mV	100	Pass Fail	***
2375-5	D Cap		21.507		1074		1200			1	Pass	
	Text and								1955.000 1955.000		Fail Pass	
Line 2	Disp 3/4	<u>"</u>	-1.601		-,669		55	7	112mV	_	☐ Fail ☐ Pass	100 mV Pol
Line 3	Disp I/2	11	-1.527		629		52	0	109mV	1	☐ Fail	RP0285
		18	-								Pass Fail	
				***						1	Pass Fail	
		- - 30						_		T	Pass	
					-	_					Fall Pass	·
		1								1	Fail Pass	
		_					_	4 =		1] Fail	
		S.								10	☐ Pass ☐ Fail	
		*								1	Pass Fall	
	-				-					1	Pass	
	-	NO PERMIT								1	☐ Fail ☐ Pass	
			-		-		_	<u> </u>		1	Fail Pass	
	1	1					1		1		Fail	

12269266091 81:11 2102/80/90

XIV. Washington State Department of Ecology 60-Day Record of Rectifier Operation

l	JST Owner		UST Facility					
Name: Flying B #29			Name: Flying B #29					
Address: 1611 Car	ryon Rd		Address: 1611 Canyon Rd					
City: Ellensburg	State: WA	ZIP: 98926	City: Ellensburg	State: wa.	ZIP: 98926			

Rectifier Manufacturer	Universal	Rectifier Model Number	SSP
Rated DC Output	48 Volts 8 Amps	Rectifier Serial Number	881571

What is the "as designed" or most recently recommended rectifier range?

SERVICE STATE OF		d m 2820	1.2		4 140	14
VOLTS:	42 TO 50	on at a g	AMPS:	.5 TO 1.5		
VOLIS.	32 10 20	200	PAIVAL S.	201010		

IIIf Volt/Amp readings recorded below are out of recommended ranges, contact your service provider.!!

Da e Inspected	Rectifier Turned On?	Tap Settings	Volts	Amps	Hour Meter	Inspector Initials	Comments
		i					
8							

		- 1	1				
	-		1		-	-	
	-		-		-		
			-				
		<u> </u>	-	-			
			1				
-			-				

UNDERGROUND STORAGE TANK

Washington State Department of **ECOLOGY**

Check those activities which apply:

Tightness Testing Checklist Retrofit/Repair Checklist Cathodic Protection Checklist

The attached Underground Storage Tank (UST) checklists are required for each of the listed activities. The checklists certify that Tightness Testing, Retrofit/Repair and/or Cathodic Protection activities are preformed and conducted in accordance with Chapter 173.360 WAC. Complete this form and the corresponding UST checklist for each activity checked above.

See back of form for instructions

1. UST SYSTEM LOCATION AND OWNER

UBI Number: 602-879-425

WA: A1363

Site/Business Name: Flying B #29

Site address: 1611 Canyon Road

Ellensburg, WA

Telephone # (509) 925-5721

County: Kittitas Zip: 98926

UST Owner/Operator: Bains, LLC

Telephone # (206) 265-0909

2. FIRM PERFORMING WORK

Service Company:

NW Environmental Solutions, Inc.

PO Box 1583

Sumner, WA. 98390

Certified Supervisor:

Kevin Wilkerson

PO Box 1583

Sumner, WA, 98390

Telephone #:

253/241-6213

IFIC Certification Numbers:

5012674-U1

UST Install/Retrofit

02/02/12

5012674-U2 5012674-U3 UST Decommissioning1 **UST Tank Testing**

11/08/10

5012674-U4

UST Cathodic Protection

01/05/12

01/06/12

5012674-U7

WA. State Site Assessment

05/23/11

Ecology is an equal opportunity and affirmative action employer. For special accommodation needs, please contact the Underground Storage Tanks Section at (360)407-7071.

ECY 010-160 (01.97)

12069266091

81:11 Z10Z/80/90

Expiration

UNDERGROUND STORAGE TANK

Tightness Testing Checklist

Site ID: 1363

Station: Flying B #29

Date of Test: July 06, 2011

Site Address: 1611 Canyon Rd. City: Ellensburg, WA. 98926

For more than four UST systems, you may photocopy this form prior to completing

Tightness testing Test method nam Test method man	e/version Pet	ro-Tite	Vaporless	US Test US Test	Alert Tec			
device is not in the tank must b	stalled, a tank e; 1) filled wit	must be tested the product to the	up to the 95% f 95% full level	by the overfill prull level. When or 2) the portion cets performance	underfill volue of the tank	umetric testir above the tan	ig metho k above	ods are used
Indicate the me for all single wa			undwater was p	oresent above th	ne bottom of	the tank dur	ing the 1	test (required
Method used fo	r release dete	tion:		4. Re	eason for cor	nducting tigh	tness te	st:
☐ Weekly manu	al gauging					release dete		
Daily manual i	The second second second second second	rol						ck into service
☐ Automatic tan		100			Tank or pipi	ng repair		
☐ Interstitial mo	nitoring)			Other: -	13700 57.		
☐ Other (describ	e)Manual Stic	k						
Type of test cond	ducted:			6. T	est method t	ype:		
☐Tank tightness t				Χ□	Overfill volu	metric		
⟨ □Line tightness to	est and/or leal	detector test			Underfill vo	lumetric		
☐Total system te	st (tank and lir	nes tested toge	ther)		Nonvalumet	ric		
					Volumetric			
TEST METHOD CH	ECKLIST		1100					
The following iten	ns shall be initi	aled by the Cer	tified Superviso	r whose signatu	ire appears o	n this form.		
Standard spec conducted? (ified in the US e.g., detecting	Trules for the o	onditions unde er hour leak rat	d to meet the pe r which the test e with probabili of no more than	was ty of	KWYes	No	N/A
		A Maria Control of the Control of th	[[- 1] [] [- 1] [] [- 1] [] [- 1] [ufacturer of the			11	
equipment ar	nd method bee	en followed wh	le the test was	being set up and	d conducted	KWYes	No	N/A
 Was the produmethods performed 	oct level in the formance stan		test within the	limitations of th	ne test	KWYes	No	N/A
If groundwater accounted for		above the botto required for sir		have the testing	procedures	Yes	No	KWN/A
	? (Note: Tank		port a failed tig	er/operator bee htness test as a		Yes release with		KWN/A ours to UST

I. TIGHTNESS TESTING METHOD

Tightness Testing Checklist (continued)

Site ID: 1363

Station: Flying B #29

Site Address: 1611 Canyon Rd. City: Ellensburg, WA. 98926

III. TANK INFORMATION CHECKLIST

1&5	2	23	
	2	3	4
_		-	
10000/8000	10000	4000	4000
Diesel (2)	Regular	Plus	Super
1 and (2) 3&5	1	1	1
S	S	S	S
	Diesel (2) 1 and (2) 3&5	Diesel (2) Regular 1 and (2) 3&5 1	10000/8000 10000 4000 Diesel (2) Regular Plus 1 and (2) 3&5 1 1

IV. LINE INFORMATION

	Line 1	Line 2	Line 3	Line 4
1. Piping type: (S) single wall; (D) double wall	S	S	S	S
2. Pump type (T) turbine; (S) suction	T	T	T	T
3. (a) If turbine, is line leak detector present? (Yes/No) (1) If present, was lead seal intact? (Yes/No/NA) (2) Line leak detector results are? (Pass/Fail) (b) If suction, check valve located at? (T)tank (P)pump	Y Pass	Y Pass	Y Pass	Y Pass
4. The numerical line test results are? (in gallons per hr)	007	004	008	008
5. Line tightness test results? (Pass/Fail)*	Pass	Pass	Pass	Pass

^{*}Inconclusive test results for tanks or piping will not be considered as a valid tightness test for the purposes of complying with UST release detection regulations.

V. REQUIRED SIGNATURES

I hereby attest, that I have been the Certified Supervisor present during the above listed testing activities, and to the best of my knowledge they have been conducted in compliance with all applicable state and federal laws, regulations and procedures, pertaining to the underground storage tanks.

Person submitting false info	ormation are subject to formal enforcement and/or	penalties under Chapter 173.360 WAC.
Date: July 6, 2011	slignature of Certifled Supervisor	Kevin Wilkerson
Date: July 6, 2011		
100	Signature of Tank Owner/Authorized Rep.	Printed Name



Underground Storage Tank Galvanic Cathodic Protection Evaluation Checklist


Instructions are on back of form


I. UST Facility							II. UST Owner					
Facility Complia	ance				-		Name: Short Stop					
UBI: 60287942							Address: 1611 S.	Very Common Service				
0011 00207012							City: Ellensburg,		te: WA	ZIP: 98929		
Facility Name:	Flvir	na B #	£29	(Phone: 509-925-5		10. 1111	211 . 00020		
Address: 1611			3.58	-			III. CP Tester					
City: Ellensburg			ıu.				Tester's Name: Kevin Wilkerson					
County: Kittata		74.					Company Name: NES, Inc .					
State: WA.	0						Address: POB 15	F 22 1114 - 1 - 1				
ZIP: 98926							City: Sumner	7.7.7.1	te: WA	ZIP: 98926		
Phone: 509-925-5721							Phone: 253-241-6		G. VVA	ZIF. 90920		
Friorie. 309-92	5-51	21					Certification Type:					
							The state of the s	There exemples	114	Fun: 01/12		
	IV. Cathodic Prote						Certification Number		J4	Exp: 01/12		
		-		10								
	Pa Fai	7673 			adequate Regulation	e, as required ons, were in a	a used to evaluate with the Washington Staccordance with a colassociation (e.g. NAC	State Undergr de of practice	ound Sto	orage Tank		
				/		- 114		Date CP Sur	vey Perfo	ormed:		
CP Tester's Sig	natu	re:	L	1/	V	Dotrofit o	r Repair Design	12/03/10				
	copi	es of	the				uried or submerged n e Underground Stora National Recognize	ge Tank Retr	ofit and F			
Company Name							Certification Number					
The state of the s		with the same	osi tnovi				Certification (Various					
Corrosion Exper	t's S	ignati	ure:		VI Cri	toria Annli	cable to Evaluat	Date:				
Continuity Test	Т	×	PA	SS 🗆			show discontinuity u		ved testi	na method		
	x	2	X	Pass	Tanks							
Neg. 850 ON	х			Fail Pass Fail	Piping	protection a	e (cathodic) potential of at least -850 mV with the cathodic on applied. This potential is with respect to a saturated copper sulfate reference electrode containing electrolyte.					
Neg. 850	х			Pass Fail	Tanks		polarized potential of opper-copper sulfate					
Instant Off	Х			Pass Fail	Piping	Potential).	opper-copper admate	reference ele	ctrode (ii	notant On		
100 mV/ Del	х			Pass Fail	Tanks	A minimum	of 100 mV of cathod	ic polarization) between	n the structure		
100 mV Pol.	Х			Pass Fail	Piping	surface and	d a stable reference e	lectrode cont	acting the	e electrolyte.		
			١	/II. Ac	tion Re	quired as	a Result of this I	Evaluation				
NONE					Cath	odic Protecti	on is adequate. No fu	irther action is	necessa	ary at this time.		
RETEST					Cath	odic Protecti	on may not be adequ	ate. Retest is	necessa	ıry.		
RETROFIT/I Remarks (Includ 32 degress, the	e typ	oe of g	gea	r; Ex:	Multi-mete	r): Fluke 73	on is not adequate. F III & MCM Miller - Not					


Structure "A"	Structure "B"	Point "A" to "B" or Fixed Location	Point d Cell	Structure "A" Fixed Voltage - >30'	Structure "B" Fixed Voltage ->30'	Point to Point or Fixed Voltage Difference	F	ass or	Method and Standard Used (e.g. RP-0285 R051)
Tank Bottom-D	Tank Bottom-U	SW Corner		.874v	871v	3 mV		Pass Fail	R051
Stip 3 Tank							E	Pass Fail	
		14-15-42					F] Fail] Pass] Fail	1
(2) Split	ale:	21					C	Pass	
								Fail Pass	
			1.129				l C	Fail Pass	JETE 1
								Fail	
] Pass] Fail	
							F] Pass] Fail	
							I	Pass Fail	
	2	Color A n	-					Pass	
								Fail Pass	
		- In 14						Fall Pass	
		100					IC	Fail	
] Pass] Fail	
						1177		Pass Fail	
						l v iti e	IC	Pass	
	IX. Galvani	c (Sacrifi	cial An	ode) Catho	dic Protecti	on System		Fail	THE PERSON NAMED IN
Structure	Contact Point	Half Cell Location	Local Voltage (ON)	Local	Remote Voltage (ON) >30'	Local Voltage (Depolarized)		Pass or Fail?	Method and Standard Used
		SW	A Street lies				×	Pass	R051
UST #1	Tank Bottom	Corner	874		853			Fail Pass	H
UST #2	Tank Bottom	Corner	871		853	10	П	Fail	R051
								Dann	
		35.31						Pass Fall	
		3=31 18						Fall Pass	
		9=31 12		1				Fall Pass Fall Pass	
		3=31 12				144		Fall Pass Fall Pass Fail Pass	
		9-39-18						Fall Pass Fall Pass Fail Pass Fail Pass Fail Pass	
		9 31 1						Fall Pass Fall Pass Fail Pass Fail Pass Fail Pass Fail	
								Fall Pass Fall Pass Fail Pass Fail Pass Fall Pass Fall Pass Fall	
								Fall Pass Fall Pass Fail Pass Fail Pass Fail Pass Fall Pass	
								Fall Pass Fail Pass	
								Fall Pass Fail	
								Fall Pass Fail	
								Fall Pass Fail	
								Fall Pass Fail	
								Fall Pass Fail	
								Fall Pass Fail Pass	

X. UST Site Plan. Diagram the UST System, including tanks, piping, and dispenser locations, approximate scale, and any other notable structures/physical features. Indicate north with arrow. Include the cathodic protection test locations used during this testing. The test points must be easily identifiable, so that testing can be reproduced and your results verified.

- V	H1641W 4 90
	80' TRASHCA!
	• VENTS
12) TANK/SPECT CON	
E FLING BH	-29
SGE A MOCHO! Projets	







SNHO 002

S2 20 100/

